

INSPECTION REPORT REVIEW  
POTENTIAL HAZARDOUS WASTE SITE

SITE NAME : DOLLAR IRON & METAL

LOCATION : HOUSTON, TEXAS

SITE NUMBER: TXD042546507

SURVEY DATE: 1986 INSPECTED BY: STATE FIT TAT OTHER: ?

LABORATORY : CLP EPA OTHER N/A

RECEIVED FROM: Betty Williamson

DATE RECEIVED: 09/02/94

SAMPLE TYPE(s): N/A

SOIL	SURFACE WATER	GROUND WATER	DRINKING WATER
off / on -site	off / on -site	off / on -site	off / on -site

CONTAMINANT(s): Organics Inorganics Radionuclides Microbiological N/A

FOLLOW UP (Y/N):

<u>N</u> (Re)Sampling Requested	<u>N</u> Locate Drinking Water Sources
<u>N</u> Further Action is URGENT	<u>N</u> Keep Site Active ("N"=No Further Action)
	<u>Y</u> Concur with Report Recommendations

SUMMARY:

According to the attached information, the site is a buyer and salvager of metal scraps. The facility only accepts empty clean drums that have never contained hazardous wastes. The waste source at the site is approximately 60 empty cleaned drums. No other sources were documented within the file information. Ground water is used as a private drinking water source within the Ground Water Migration Pathway's target distance limit. The distances to the private drinking water wells are not known. There is a possibility that ground water is being used as a municipal drinking water source; however, documentation has not been obtained to substantiate this claim. Drainage from the site flows into the Sims Bayou. The distance of the overland flow route is not known. Target information for Sims Bayou has not been documented within the 15-mile Surface Water Migration Pathway's target distance limit.

RECOMMENDATION:

Based on the available information, it appears that the potential for ground or surface water contamination from this site is very unlikely at this time.

Concurrence:

Hillol K. Ray II, 23, 94  
ENGINEER/REVIEWER

90067010

